

Natural Power - Blade Defect Inspections - Onshore Wind Case Study



Project:	Wind Farm Blade Inspections – N.E. France
Client:	Confidential
Project Description:	Ground based external blade inspections to 23 WTG's
Services Provided:	External blade inspection services to 23 No. Gamesa G97-2.0MW
Performance delivered, including strategic value to the client:	<p>The inspections team was only given a short mobilisation period to site to enable a defect finding campaign that followed potentially serious defect identification.</p> <p>The campaign was completed within stringent client timescales (5 days max). An international effort was required, liaising with both French and Spanish speaking technicians to allow for turbine control and manipulation.</p>



For more information contact:
Michael McQueenie
Senior Account Manager
michaelm@naturalpower.com

For full details on our ISO and other certifications, please visit: naturalpower.com/company